ROBERT A. VOGEL, M.D. HEALTH COMMISSIONER

513 - 225-4443

## MONTGOMERY COUNTY COMBINED GENERAL HEALTH DISTRICT



**COUNTY GOVERNMENT PLAZA** 451 WEST THIRD STREET DAYTON, OHIO 45422

DAVID ULRICH, D.D.S. PRESIDENT MRS. MARTHA CARRICK . VICE-PRESIDENT HERMAN ABROMOWITZ, M.D. MRS. MARIE DAUGHERTY JOHN DOAN MRS. VERDREE HARRIS W. J. LEWIS, M.D. EDWARD RAUSCH

CHARLES F. WILCHER, JR., D.O.

BOARD OF HEALTH

0000023

March 24, 1980

RECEIVED

MAR 2 6 1980

Onio Environimental Protection Agency SOUTHWEST DISTRICT

Filo Mondgomery les Solid Waste

Mr. Russell A. Gilmore III The Peerless Transportation Co. 214 South Perry Street Dayton, Ohio 45402

Solid waste disposal Re:

Dear Mr. Gilmore:

We recently learned that you are transporting white plaster dust from the Ohio Precision Castings, Inc. and disposing of it in your foundry sand disposal site on Brandt Pike. In addition we learned you anticipate transporting fly ash from Cargill, Inc. to this same site.

The Ohio EPA has determined that both these industrial wastes . are "solid waste" and therefore must be disposed of in a licensed landfill. Your foundry sand disposal site is not licensed.

The fly ash can be taken to any licensed landfill that can handle In Montgomery County the following sites which are suitable:

- North Sanitary Landfill, 4220 Pinnacle Rd., Moraine 1.
- 2. Powell Road Landfill, 4060 Powell Rd., Wayne Twp.
- South Dayton Landfill, 1975 Springboro Pike, Moraine 3.
- Moraine Materials Dryden Rd. Complex, Rear of 3265 Dryden 4. Rd., Moraine
- Moraine Materials, Hurt B Pit, Farmington Rd., Miami Twp. 5.

The white plaster dust may only be taken to the first three licensed landfills in Montgomery County.

Mr. Russell A. Gilmore III March 24; 1980 Page Two

This letter shall be considered an official order to dispose of all fly ash and white plaster dust in a licensed landfill within seven (7) days. Authority for this order can be found in Section 3734.05, Ohio Revised Code.

If you have questions concerning this order, please call 225-4443.

Sincerely,

John H. Bindeman Systems Analyst

2. Budeman

JHB/bab

cc: Joe Moore